
460/ 461 SURFACE BOLTS (8" & 12")

FOR STEEL OR WOOD DOORS

460 SHOWN BELOW

NOT TO SCALE

12-10-14



DRILL ALL MOUNTING HOLES FOR #8 X 1-1/4" FL HD SMS SCREWS (8) SCREWS INCLUDED

(FIG.3) TOP BOLT/ 'L' STRIKE STOP/ PUSH SIDE MOUNTED (OUT SWINGING DOOR)


DOOR

TEMPLATE: 939314

REV. 0


[10.7]

STOP




- MODEL# 460 5-3/4" [203.2] [146.1] 9-3/4"" 461 12" [247.7] [304.8] (A) = TOP/ BOTTOM EDGE
- OF DOOR TO CENTER OF **GRIP END BOLT GUIDE** (HINGE SIDE MOUNTED AND BOTTOM BOLT. SEE FIG.3 FOR STOP SIDE MOUNTED TOP BOLT) (B) = OVERALL BOLT LENGTH
- (C) = CENTER OF EDGE END BOLT GUIDE TO CENTER OF

GRIP END BOLT GUIDE



(FIG.2) BOTTOM BOLT/ MORTISE STRIKE




- 1. DETERMINE SIDE OF DOOR TO WHICH BOLTS ARE TO BE APPLIED.
- 2. DRILL AND TAP MOUNTING HOLES IN DOOR FOR BOLT GUIDES.
- 3. MOUNT BOLT ASSEMBLY ONTO DOOR.
- 4. SELECT APPROPRIATE TOP OR BOTTOM STRIKE. ALIGN EACH STRIKE WITH BOLT AND ATTACH WITH REMAINING SCREWS.


NOTES:

- 1. DIMENSIONS IN INCHES [MM]
- 2. HOLLOW METAL DOOR AND FRAME SHOULD BE PROPERLY REINFORCED WITH A 3/16" [4.8] MINIMUM THICKNESS PLATE.
- 3. ALWAYS CHECK PDQ WEBSITE FOR THE MOST RECENT TEMPLATE REVISION AT WWW.PDQLOCKS.COM

(FIG.5) TOP BOLT/ 'L' STRIKE HINGE/ PULL SIDE MOUNTED (IN SWINGING DOOR)



(FIG.6) TOP BOLT/ 'L' STRIKE STOP/ PUSH SIDE MOUNTED (OUT SWINGING DOOR)





PDQ Manufacturing 2754 Creek Hill Rd. Leola, PA 17540 800-441-9692 Fax: 717-656-6892 www.pdqlocks.com